



\* 1-4 (Strang / Colonne montante / Montante)  
 X (Entfernen Sie J1 / Retirez le J1 / Rimuovi J1)

Info: Verdrillte kabel verwenden / Utiliser des câbles torsadés  
 Utilizzare cavi twistati Art.336904 - Eldas 101 282 009

21 INT 1.2/00

41 INT 1.2/06














21 TAB 1.1/00

41 TAB 1.1/06

\* 1-4 (Strang / Colonne montante / Montante)  
 X (Entfernen Sie J1 / Retirez le J1 / Rimuovi J1)

Info: Verdrillte kabel verwenden / Utiliser des câbles torsadés  
 Utilizzare cavi twistati Art.336904 - Eldas 101 282 009



\*1  
 21 INT 1.1/00

\*2  
 41 INT 1.1/06