




\* 1-4 (Strang / Colonne montante / Montante)


Info: Verdrillte kabel verwenden / Utiliser des c° bles torsadés  
 Utilizzare cavi twistati Art.336904 - Eldas 101 282 009

21 INT 1.2/00



21 TAB 1.1/00

41 INT 1.2/06



41 TAB 1.1/06



0	1	2	3	4	5	6	7	8	9	10
---	---	---	---	---	---	---	---	---	---	----

\* 1-4 (Strang / Colonne montante / Montante)

Info: Verdrillte kabel verwenden / Utiliser des c° bles torsadés  
 Utilizzare cavi twistati Art.336904 - Eldas 101 282 009

21 INT 1.3/00

41 INT 1.3/06



21 INT 1.1/00

41 INT 1.1/06

0	1	2	3	4	5	6	7	8	9	10
---	---	---	---	---	---	---	---	---	---	----

\* 1-4 (Strang / Colonne montante / Montante)

Info: Verdrillte kabel verwenden / Utiliser des c°bles torsadés  
 Utilizzare cavi twistati Art.336904 - Eldas 101 282 009

